

SSM 51533

2021-2023 Bronco (U725N) (G1)

2021-2023 Bronco - B15F1:15 In The PDM With No Warning Indicators

Some 2021-2023 Bronco vehicles may exhibit a diagnostic trouble code (DTC) B15F1:15 code stored in memory of the passenger door module (PDM). This code was intended for a right mirror indicator light emitting diode (LED) feature on vehicles and currently is not used. This code may be due to PDM module software. If the PDM module exhibits DTC B15F1:15, the DTC should be ignored.